


# WIRING SCHEMATIC FOR SINGLE PHASE SUPPLY TO 3 PHASE MOTOR VIA AN INVERTER

Q12-010 rev 01



# WIRING DIAGRAM FOR SINGLE PHASE SUPPLY TO 3 PHASE MOTOR VIA AN INVERTER

